

Release Notes

GEOSPATIAL
FEBRUARY 2023

TRIMBLE X7 Firmware Version 2.5.100

Introduction

Trimble announces the release of firmware version 2.5.100 for the Trimble X7 3D laser scanner. This firmware update is for production purposes only. Production will install 2.5.100 on new instruments and no action is required if a customer receives an instrument with this firmware version.

Overview

- General changes for production line to support new board versions

Firmware 2.5.12 vs 2.5.100

All features of the current released version of firmware 2.5.12 are included in version 2.5.100. Trimble Installation Manager (TIM) will prohibit the installation of earlier firmware versions on instruments running 2.5.100. The following message will appear. Firmware 2.5.100 will update later when newer versions become available on TIM.



The selected firmware package R2.5.12 is below the required minimal version R2.5.100.
The installation is rejected.

Customers running firmware 2.5.12 are not required to update. Customers running firmware versions older than 2.5.12 are encouraged to update.

Requirements

Customers should install Trimble Perspective version 3.1.1 to ensure compatibility with firmware versions 2.5.12 and 2.5.100.

For more information

For more information, contact your local Trimble Distribution Partner.

© 2023, Trimble Inc. All rights reserved. Trimble and the Globe & Triangle logo are trademarks of Trimble Inc., registered in the United States and in other countries. All other trademarks are the property of their respective owners.